



Inspection Detail



Client:	HDD Broker		
Inspected by:			
Location of Inspection:			
Phone No / Email:			
Date of Inspection:	8/20/2025	Job#:	
Year:	2018	Make:	Ditch Witch
Model:	JT20	VIN/SN:	

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details

Unit Information

Hours:	4,824	Date:	N/A
--------	-------	-------	-----

General Body

Paint condition:	See Notes	Panel dents:	No	Corrosion:	No
Dents/Bends:	No	Visible leaks:	No	Operator console pivot/lock:	No Damages Observed
Operator's Seat:	No Damages Observed	Operator Console Joysticks, switches, gauges:	See Notes	Fresh water tank (if applicable):	N/A

Safety Equipment

Operator's presence switch (seat):	No Damages Observed	Safety switches:	No Damages Observed	Red safety bars (rod loader extensions):	No Damages Observed
Work lights:	N/A	Strike alert/ground wire:	No Damages Observed	Safety decals:	See Notes

Breakout System

Breakout jaw wear:	No Damages Observed	Cylinder and hose condition:	No Damages Observed	Pins/bushings slop:	No Damages Observed
Front Stakedown System:	No Damages Observed	Auger condition:	No Damages Observed		

Main Drive System

Tracks (steel or rubber):	Rubber	Track condition:	See Notes	Sprockets/rollers:	No Damages Observed
---------------------------	--------	------------------	-----------	--------------------	---------------------

Rear Outriggers

Cylinder and hose condition:	No Damages Observed	Pins and bushings:	No Damages Observed	Bent/broken parts:	No
------------------------------	---------------------	--------------------	---------------------	--------------------	----

Carriage

Wear pads/carriage slop:	No Damages Observed	Motors and hoses condition:	No Damages Observed	Rack and pinion condition:	No Damages Observed
--------------------------	---------------------	-----------------------------	---------------------	----------------------------	---------------------

Engine Details

Fluid level and condition:	Low Level / Good Color	Visible leaks:	No	Belts and pulleys:	No Damages Observed
Engine mounts:	No Damages Observed	Radiator/hoses:	No Damages Observed		

Operation

Engine start and idle:	Yes	Engine smoke:	No	Engine noises (tick/knock):	No
Rear outrigger operation:	No Damages Observed	Main rack tilt:	No Damages Observed	Front stakedown rotation/up/down:	No Damages Observed
Breakout vices open/close/rotate:	No Damages Observed	Rod loader lift/shuttle/alignment:	No Damages Observed	Carriage traverse (thrust/pullback):	No Damages Observed
Rotation motor fwd/reverse:	No Damages Observed	Mud pump on/off:	No Damages Observed		

Drill Rods

Rod count:	40	Bent rods:	No	Thread condition:	No Damages Observed
Corrosion:	See Notes				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tracks					
Left Track Condition:	See Notes	Left Tire Brand:	Obstructed	Left Tire Size:	Obstructed
LeftTrack Tread Depth Measurement:	24/32"	Left Track Rollers:	No Damages Observed		
Right Track Condition:	See Notes	Right Tire Brand:	Obstructed	Right Tire Size:	Obstructed
RightTrack Tread Depth Measurement:	24/32"	Right Track Rollers:	No Damages Observed		
Observations / Comments					
The unit starts and operates.					

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



Wear and Tear Items

Item Name	Item Comments
Hydraulic Oil	Low hydraulic oil level.
Sheet Metal	There is a sheet metal loose near the right track.
Righ Track	The track is worn, has small gouges and cracks.
Left Track	The track is worn, has some areas slightly damaged and small gouges.
Strip Metal Sheet	There is a strip of metal sheet dented on the left side near the hydraulic hoses.
Hydraulic Compartment Vents	The vent frame appears to be starting to crack.
Engine Compartment Grille	There is a strip of metal dented from the grille.
Engine Compartment Seal	The seal is damaged.
Coolant	Low coolant level.
Drill Rod Frame	The drill rod frame is damaged.
Remote Joystick	The joystick is dirty, cover is peeling, and the box is damaged.
Engine Compartment	The engine compartment has a dent.
Switch Cover	There is a switch cover damaged near the ignition controls.
Keys	The unit keys are rusty.
Plate Screw	There is a screw missing from the plate near the armrest.
Instrument Cluster	The screws are rusty, the panel is scratched, and the paint is faded and peeling in some areas.
Warning Light	There is a warning light on the dashboard.
Paint	The panel paint is faded and body paint has scratches.
Emblems & Decals	There are emblems missing and some decals damaged.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.