



CONDITION REPORT

TRENCHLESS EQUIPMENT

MAKE: Vermeer		DATE:	
MODEL: 23x30 S3		GENERAL OVERALL CONDITION	
SERIAL:		(Higher Numbers are Better) 1 2 3 4 5	
HOURS: 2625		☐ ☐ ☐ ☒ ☐	
YEAR: 2017		INSPECTION RATINGS KEY	
CUSTOMER:		5 = Excellent cond.-New or recently replaced parts.	
CONTACT:		4 = Operates well, shows less then average wear.	
PHONE #		3 = Operates and is in avg. condition for age and hrs, minimal repairs.	
EVALUATOR:		2 = Operates but needs repairs.	
		1 = Repairs necessary prior to use.	

DIRECTIONS / CUSTOMER INFO.

ENGINE	1	2	3	4	5	N/A	NOTES
(Higher Numbers are Better)							
Fluid level and condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full			
Perform Oil Sample	☐ YES			☒ NO			
Engine Noise	☐ YES			☒ NO	☐		
Engine Smoke	☐ YES			☒ NO	☐		
Visible Leaks	☐ YES			☒ NO	☐		
Gauges Instruments	☐	☐	☐	☐	☒	☐	
Belts and Pulleys	☐	☐	☐	☐	☒	☐	
Idle and Throttle Quality	☐	☐	☐	☐	☒	☐	
Engine Mounts and Slides	☐	☐	☐	☐	☒	☐	
Radiator / Hoses	☐	☐	☐	☐	☒	☐	
Any Missing Parts	☐ YES			☒ NO			

SAFETY EQUIPMENT

	1	2	3	4	5	N/A
(Higher Numbers are Better)						
Seat Belt	☐ YES			☐ NO	☒	
Operator Presence Switch (seat)	☒ YES			☐ NO	☐	
Safety Switches	☐	☐	☐	☐	☐	☒
Red Safety Bars/ E- stops	☐	☐	☐	☐	☒	☐
Work Lights	☒ YES			☐ NO	☐	
Strike Alert / Ground wire	☐	☐	☐	☐	☒	☐
Decals In Place / Legible	☒ YES			☐ NO	☐	
Any Missing Parts	☐ YES			☒ NO	☐	

BODY PANELS

(Higher Numbers are Better)	1	2	3	4	5	N/A
Paint	☐	☐	☐	☐	☒	☐
Panel Dents	☐ YES		☒ NO		☐	
Rust	☐ YES		☒ NO		☐	
Frame	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES		☒ NO			

OPERATION FUNCTION

(Higher Numbers are Better)	1	2	3	4	5	N/A
Gearbox Rotation at Full RPM	☐	☐	☐	☐	☒	☐
Rollers	☐	☐	☐	☐	☒	☐
Drilling Fluid Shutoff Ball Valve	☐	☐	☐	☐	☒	☐
Throttle Control Front & Rear	☐	☐	☐	☐	☐	☒
Front Vice	☐	☐	☐	☐	☒	☐
Front Vice Cylinder Pins & Frame	☐	☐	☐	☐	☒	☐
Rear Vice	☐	☐	☐	☐	☒	☐
Rear Vice Cylinder Pins & Frame	☐	☐	☐	☐	☒	☐
Rear Vice Tilt	☐	☐	☐	☐	☒	☐
Vice Jaws Damage And Wear	☐ YES		☒ NO		☐	
Rear Tilt Cylinder	☐	☐	☐	☐	☒	☐
Right Stake down Up/Down+ Rotation	☐	☐	☐	☐	☒	☐
Rotation	☐	☐	☐	☐	☒	☐
Pins &O rings	☐	☐	☐	☐	☒	☐
Left Stake down Up/Down+ Rotatation	☐	☐	☐	☐	☒	☐
Rotation	☐	☐	☐	☐	☒	☐
Pins & O rings	☐	☐	☐	☐	☒	☐
Console Pivots	☐	☐	☐	☐	☒	☐
Rotation Lever, Self Center	☒ YES		☐ NO		☐	
Thrust Lever, Self Center Thrust	☒ YES		☐ NO		☐	
Rod Loader Arms In/Out	☒ YES		☐ NO		☐	
Water Pump On/OFF	☒ YES		☐ NO		☐	
Water Pump GPM Up/Down						
Chain & Chain Pins	☐	☐	☐	☐	☐	☒
Chain Adjustment	☐	☐	☐	☐	☐	☒
Wear Pads (Drive Chuck)	☐	☐	☐	☐	☒	☐
Rack And Pinion	☐	☐	☐	☐	☒	☐
Pinion Gears	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES		☒ NO			



TRACKS AND FRAME

(Higher Numbers are Better)	1	2	3	4	5	N/A
Right Track Forward/Reverse	☐	☐	☐	☐	☒	☐
Track Chain Rollers	☐	☐	☐	☐	☐	☒
Check Track Sprockets	☐	☐	☐	☐	☒	☐
Left Track Forward/Reverse	☐	☐	☐	☐	☒	☐
Track Chain Rollers	☐	☐	☐	☐	☐	☒
Check Track Sprockets	☐	☐	☐	☐	☒	☐
Rollers	☐	☐	☐	☐	☒	☐
Rubber Pads	☐	☐	☐	☐	☐	☒
Track Adjustment	☐	☐	☐	☐	☒	☐
Rear Outrigger Up/Down	☐	☐	☐	☐	☒	☐
Track Extension	☐	☐	☐	☐	☐	☒
Tilt Pivot	☐	☐	☐	☐	☒	☐
Tilt Cylinder	☐	☐	☐	☐	☒	☐
Track Condition	☐	☒	☐	☐	☐	☐
Any Missing Parts	☐ YES		☒ NO			

Tracks need replacement eventually.

UNDER CARRIAGE

(Higher Numbers are Better)	1	2	3	4	5	N/A
Track Frame Cracks, Repairs	☐ YES		☒ NO		☐	
Rollers / Idlers	☐	☐	☐	☐	☒	☐
Sprockets	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES		☒ NO			

ROD AND ROD BOX

(Higher Numbers are Better)	1	2	3	4	5	N/A
Number Of Rods / Size	Number of Rods: <u>400</u>					Size: <u>2.375</u>
Check For Wear %	%					
Bent Rods #	#					
Check Threads W/gauge	☐ YES		☒ NO			
Check Shoulders W /gauge	☐ YES		☒ NO			
Rod Wipers / Holder Damage	☐	☐	☒	☐	☐	☐
Rod Box	☐	☐	☐	☐	☒	☐
Top Pins / Bottom Pins	☐	☐	☐	☐	☒	☐
Rod Box Damage	☐	☐	☐	☐	☐	☒
Rod Box Cover	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES		☒ NO			

TOOLING / LOCATOR

(Higher Numbers are Better)	1	2	3	4	5	N/A	
Drill Head		☒ YES		☐ NO		☐	
Starter Rod		☒ YES		☐ NO		☐	
Hex Collar		☒ YES		☐ NO		☐	
Duck Bills		☐ YES		☐ NO		☒	
Reamers		☐ YES		☐ NO		☒	
Reamer Sizes					inches		
Wash Wand	☐	☐	☐	☐	☒	☐	
Locator	☐	☐	☐	☐	☐	☒	SN#
Remote	☐	☐	☐	☐	☐	☒	SN#
Probes Color	☐	☐	☐	☐	☐	☒	SN#
Probes Heat Indicator	☐	☐	☐	☐	☐	☒	
Cones	☐	☐	☐	☐	☒	☐	

CAB

(Higher Numbers are Better)	1	2	3	4	5	N/A	
A/C		☐ YES		☐ NO		☒	
Heater		☐ YES		☐ NO		☒	
Glass	☐	☐	☐	☐	☐	☒	
Wipers	☐	☐	☐	☐	☐	☒	
Doors	☐	☐	☐	☐	☐	☒	
Multi-Function Display	☐	☐	☐	☐	☐	☒	

HYDRAULIC SYSTEM

(Higher Numbers are Better)	1	2	3	4	5	N/A	
Hydraulic Fluid Condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full			
Pump Pressure / Flow							PSI.
Visible Leaks		☐ YES		☒ NO		☐	
Hoses and Fittings	☐	☐	☐	☐	☒	☐	
Operation of Controls	☐	☐	☐	☐	☒	☐	
Hydraulic Tank and Caps	☐	☐	☐	☐	☒	☐	
Perform Oil Sample		☐ YES		☒ NO			

Salesman: _____

PICTURES☒ YES ☐ NO

NOTES

MIXING SYSTEM

SERIAL:

MODEL:

ENGINE**NOTES**

(Higher Numbers are Better)

	1	2	3	4	5	N/A
Fluid level and condition	☐ 1/4	☐ 1/2	☐ 3/4	☐ Full		
Engine Noise	☐ YES		☐ NO			
Engine Smoke	☐ YES		☐ NO			
Visible Leaks	☐ YES		☐ NO			
Idle and Throttle Quality	☐	☐	☐	☐	☐	
Engine Mounts	☐ YES		☐ NO			
Any Missing Parts	☐ YES		☐ NO			

TANK

(Higher Numbers are Better)

	1	2	3	4	5	N/A
Condition of Tank	☐	☐	☐	☐	☐	
Hoses	☐	☐	☐	☐	☐	
Caps	☐	☐	☐	☐	☐	
Ball Valves	☐	☐	☐	☐	☐	
Hopper	☐	☐	☐	☐	☐	
Any Missing Parts	☐ YES		☐ NO			

PUMP

(Higher Numbers are Better)

	1	2	3	4	5	N/A
Condition of Pump	☐	☐	☐	☐	☐	
Pump Noise	☐ YES		☐ NO			
Visible Leaks	☐ YES		☐ NO			
Packings	☐	☐	☐	☐	☐	
Any Missing Parts	☐ YES		☐ NO			

TRUCK

SERIAL:

MODEL:

MILAGE:

(Higher Numbers are Better)

	1	2	3	4	5	N/A
Cab and Body	☐	☐	☐	☐	☐	
Paint	☐	☐	☐	☐	☐	
Panel Dents	☐ YES		☐ NO			
Rust	☐ YES		☐ NO			
Any Missing Parts	☐ YES		☐ NO			

TRAILER

SERIAL:

MODEL:

(Higher Numbers are Better)

	1	2	3	4	5	N/A
Paint / Rust	☐ YES		☐ NO			
Damage	☐	☐	☐	☐	☐	
Tires						
Lights	☐ YES		☐ NO			
Brakes	☐	☐	☐	☐	☐	

This inspection report has been furnished solely for informational purposes and it is not to be construed in any way as a warranty or guarantee on the condition of the equipment. Buyers should confirm the accuracy of this report to their satisfaction prior to purchase. Buyer agrees to hold harmless HDD Broker, the seller and the inspecting agent.